

EXHIBIT 3



March 21, 2003

Mr. Edward Cottingham
Ness Motley
28 Bridgeside Boulevard
Mt. Pleasant, SC 29464

RE: Church of the Most Holy Redeemer - Basement

Dear Mr. Cottingham:

The following is a bulk sample from the above referenced project in which we have identified the manufacturer of the asbestos containing surface treatment material.

	<u>Sample #</u>	<u>Manufacturer / Product</u>
1)	1	W.R. Grace / Zonolite Acoustical Plastic

If you have any questions regarding this report, please do not hesitate to give me a call.

Sincerely,

A handwritten signature in black ink, appearing to read "WEL/mac".

William E. Longo, Ph.D.

WEL/mac

cc: M30677-001

MATERIALS ANALYTICAL SERVICES, INC.
PLM ANALYSIS

Proj#-Spl#: M30677-001 Analyst W.B. Egeland Date: 3/17/03
 ClientName: Law Offices of Ness, Motley ClientSpl: 1
 Location:
 Type_Mat: basement ceiling
 Gross Tan. Flakes and books as well as fiber bundles with a fine matrix throughout. White paint on surface.
 Visual:

OPTICAL DATA FOR ASBESTOS IDENTIFICATION

Morphology	Wavy		
Pleochroism	None		
Refract Index	1.555/1.548		
Sign	+		
Extinction	Parallel		
Birefringence	Low		
Melt	No		
Fiber Name	Chrysotile		

ASBESTOS MINERALS**EST. VOL. %**

Chrysotile.....	15
Amosite.....	
Crocidolite.....	
Tremolite/Actinolite.....	
Anthophyllite.....	


OTHER FIBROUS COMPONENTS

.....
.....
.....
.....
.....

NON FIBROUS COMPONENTS

Vermiculite	70
.....
.....
.....
Binder	15

Effervescence: Weak and isolated.Binder Description: Fine-grained aggregateComments: No starch observed



MATERIALS
ANALYTICAL
SERVICES

MINERAL ANALYSIS SHEET


ITEM ANALYSIS: BULK ANALYSIS
PROJECT: CHURCH OF THE HOLY REDEEMER
SAMPLE NUMBER: 17306778-001
SAMPLE ID: 1
DATE OF ANALYSIS: 3/20/03
ANALYST: L.A. Sch


ASBESTOS MINERALS:


CHRYSTOCOLAE (ADS) (DIF)

OTHER COMPONENTS:

OTHER COMMENTS:







M50677

LAW OFFICES

NESS, MOTLEY
PROFESSIONAL ASSOCIATION

28 BRIDGESIDE BOULEVARD
MOUNT PLEASANT, SOUTH CAROLINA 29464
POST OFFICE BOX 1792
MOUNT PLEASANT, SOUTH CAROLINA 29465
843-216-9000 FAX # 843-216-9450
E-MAIL: NESSMOTLEY@NESSMOTLEY.COM

OTHER OFFICES
CHARLESTON, SOUTH CAROLINA
BARNWELL, SOUTH CAROLINA
PROVIDENCE, RHODE ISLAND
NEW ORLEANS, LOUISIANA
RALEIGH, NORTH CAROLINA

EDWARD B. COTTINGHAM, JR.
DIRECT DIAL: (843) 216-9148
FAX: (843) 216-9440
E-MAIL: ecottingham@nessmotley.com

March 10, 2003

Via Federal Express

William Longo PhD
Materials Analytical Services
3945 Lakefield Court
Suwanee, GA 30024

RE: W.R. Grace Bankruptcy
Sample from The Church of the Most Holy Redeemer

Dear Bill:

Enclosed is a sample that I received from a client in Minnesota. This sample was taken from the ceiling of the basement of the church on March 7th and forwarded to me via Federal Express. Would you please analyze this sample for product ID and return the result to me as soon as possible.

Please call if you have any questions.

Sincerely,



Edward B. Cottingham, Jr.

EBC:dlg
Enclosure

Received 3-11-03
Amalgam

Page 1 of 1

MATERIALS ANALYTICAL SERVICES, INC.
CHAIN-OF-CUSTODY

CLIENT: Law Offices of Ness, Motley**MAS JOB:** M30677**CONTACT:** Edward Cottingham**DATE RECEIVED:** 3/11/03**PHONE:** (843) 720-9000**SUBMITTED BY:** Ed Cottingham**CLIENT JOB NAME:** Church of the Most Holy Redeemer**TRANSPORT:** FedEx**CLIENT JOB#:****RECEIVED BY:** dmazzaferro**CLIENT DOC(S):** Letter of transmittal**CONDITION:** good**FAX NUMBER:** (843) 577-6361

MAS #	CLIENT ID	VOLUME	TYPE	MATERIAL	MAS #	CLIENT ID	VOLUME	TYPE	MATERIAL
001	1			basement ceiling					
LOCATION									

INITIAL FILE REVIEW: _____**DATE:** _____**SAMPLE PREP BY:** _____**DATE:** _____**SAMPLE ANALYSIS BY:** _____**DATE:** _____**COMMENT:** _____

Materials Analytical Services, Inc.

3945 Lakefield Court

Suwanee, Georgia 30024

(770) 866-3200